



add solder to JP2
to close connection



remove solder from JP1
to open connections